

Customer Name: HAMILTON	Date: 18/06/25
Customer Reference: 8890	Fitter: Gary
Salesperson: GREAME	Salesperson called: No
Blind Type and number: SHUTTER (LIVING L)	
Fault Description: BACK OF DOOR IS DAMAGED, PHOTO'S SENT TO EMAIL	
Action to correct: REORDER DOOR	
Problem fixed on site:	
Further action required:	

# Fault Report