

EO 5293  
MAK/R.

# Fault Report

<b>FITTER NAME:</b> Gary	<b>FITTING DATE:</b> 7/8/25
Customer Name: MAK	
Customer Ref: 5293	
Salesperson: Gary	Salesperson called <input checked="" type="radio"/> Yes/No
Blind Type and number: Skylight Motorised Pleat	
Problem fixed on site: Yes/No	
Fault Description Blind to be re-corded on site and new end caps	
Action to Correct:- As Above	