

RAIN 9120
JORDAN / R1

Customer Name Jordan	Date: 13/08/25
Customer Reference: 9120	Fitter: Gary
Salesperson: Ronnie	Salesperson called: No
Blind Type and number: 1 x Roller	
Fault Description: Roller made in Glade as per matrix but should be Gable	
Action to correct: Remake blind in Gable as order states	
Problem fixed on site:	
Further action required:	

Fault Report