

ED 5199  
ELLIOTT/R

Customer Name Elliott	Date: 14/08/25
Customer Reference: 5199	Fitter: Gary
Salesperson: Gary	Salesperson called: No
Blind Type and number: 1 x Shutter Door	
Fault Description: Midrail is in incorrect position in Office (770x1290)	
Action to correct: Please order Door only with the Midrail @ 680mm	
Problem fixed on site:	
Further action required:	

# Fault Report