


Customer Name <del>Hand</del> BROWN	Date: 22/10/25
Customer Reference: 9170	Fitter: Gary
Salesperson: Ronnie	Salesperson called: No
Blind Type and number: 1 x Curved track	
Fault Description: Curve wrong	
Action to correct: Please re order Track to drawing	
	
Problem fixed on site:	
Further action required:	

# Fault Report

ORDER TOTAL = €375  
DEP PD = 29/8/25