

ED 5289  
Henderson 1A

# Fault Report

SR EOI

<b>FITTER NAME:</b> Scott	<b>FITTING DATE:</b> 6/1/25
Customer Name: Henderson	
Customer Ref: ED 5289	
Salesperson: CARY	Salesperson called: Yes/No <input checked="" type="radio"/>
Blind Type and number: Vertical. Slot - Corerra cream OSPVC 131	
Problem fixed on site: Yes/No <input checked="" type="radio"/>	
Fault Description Slot is broken from the top. Can't be put back up New slot required.	
Action to Correct:-	

ORDER TOTAL = £385  
DEP PD = 17/6/25

