

SR EOI

Fault Report

Customer Name: LANNIGAN	Date: 03-02-26
Customer Reference: E05396	Fitter: SCOTT / BERANE
Salesperson: RONNIE	Salesperson called: Yes/No
Order Inputting Error <input type="checkbox"/>	Mismeasure <input type="checkbox"/>
Production Error <input type="checkbox"/>	Supplier Error <input checked="" type="checkbox"/>
Fitting Error <input type="checkbox"/>	
Problem fixed on site: Yes/No <input checked="" type="checkbox"/>	
Blind Type and number: Rouge.	
Fault Description: LIGHT COMING THROUGH FABRIC AND DROOPY PUCKERS AT BOTTOM	
Action to correct: REMAKE ON POLARIS D/O GRAPHITE	

ORDER TOTAL = £193.00
DEP PD = 15/1/26

