

# NON CONFORMITY REPORT

DATE 22/5/18 ORDER NO. 11922 NAME JACKSON

## DETAILS OF NON CONFORMITY.

1 of Duettes on Patio Doors - fabric has split  
 - CF HAS SENT PHOTO TO SALES

SORTED

**ACTION TAKEN.** Call to see - take photo?

Remake FAULTY

EMMAILED  
25/5/18

~~at 230 PM Weds Tues 22<sup>nd</sup> May~~

930 Weds 27<sup>th</sup> June

C-18-10626

**SIGNED...**

1302 Thurs 12<sup>th</sup> July

WAITING FOR

2nd Remake

Replacement blind has fault in gear wire, and cords are twisted internally.

From Frank  
C18-107920

Speak to Chris

--	--	--	--	--	--

Special Instructions

Mr/Mrs/MS C. JACKSON  
 Address 10 ROERMOUNT ROAD  
SUREAU WHALLAN VIEW  
PEEL Post Code IM5 1QN  
 Telephone (H) 844032 (W) \_\_\_\_\_  
 Mobile \_\_\_\_\_  
 Email colanes@max.net

DATE RECEIVED <u>8/3/18</u>	L TIME <u>10am Weds 28th</u>
OUR ORDER No. <u>11922</u>	DATE, FIX & TIME <u>3pm Tues 27<sup>th</sup> Mar</u>
QUOTE I.D: <u>6/3/18</u> <u>2726. MW</u>	FIXING TIME
WORKS ORDER No.: <u>11922</u>	PURCHASE ORDER NO: ID NO: <u>37</u>

CUSTOMER SIGNATURE: