Staff Name Andrew

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS8699	Surveyors	Mr & Mrs. Shacklock, 27 WINDERMERE DRIVE, LAKESIDE GARDENS, ONCHAN, ISLE OF MAN, IM3 2DN, 01624 624911, bob_shacklock@yahoo.co.uk		05-06-2023	PM 12.15

Notes : W Ex Snow in the bathroom.

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Shower	1	1165	R	1132	2/2	WOOD EXP SNOW	SO?		W	TOP FIX DRILL	TILES
Room					8						NOT PORC
						FLAT PELMET					
Study	1					REFIX CUSTOMERS OLD BLIND				" " "	
						(WOOD VEN)					
						CUSTOMER KNOWS IT					
						GOING TO BE NARROW IN					
						WIDTH					