

Staff Name Andrew  
 Order No TS8813  
 Surveyors

Contact Address Mrs. Anne Cowin, 9 Howstrake Drive, Onchan, Isle Of Man, IM3 1BP, 673555.

Customer Ref

Date 03-07-2023

Time PM

Notes : Repair or replace - take vert and roller book. Lady is 91 -

Work Diary

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
logp	1	<del>347</del> 3595	R	1360	2308	1 RAKE CURRY	127		W	24 Spur	ON COEN (X CHAIN)
Hall	1	1075	R	1900	n	<del>Category</del> CURTAIN SNOOCHER P/B	32		W	R15/C Smd	USE CURTAIN
Shower	1	1074	R	1000	n	RE 486 Vert Remove ON DIRECTIONAL	n		n	(OFF F)	HOURS X BETS
						PR NEW ONE					
						REMOVE AND BRINDS					
						+ TAKE 4x5" HOURS					
Dim	1					5" HOURS INSERT ✓					DONE