Staff Name Andrew

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS9287	Surveyors	Mrs. Miller, 10 Lyndale Avenue, Peel, Isle Of Man, IM5, 842787, phyllis.miller@manx.net		16-10-2023	16:00

Notes : Repair or replace vertical?

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Backhouse	1	1360	R.	1595	2 6 8	2/L. Arora WHITE	89		W	RA/SPOT	CORD A CHAIN
											~~HOT~~ Please,
						IN STOCK?					USE OLD
						CORD a CHAIN @ 1120 Please.					HOLES
											IF POSS
											Remove OLD
											Vert