

Staff Name Chris

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS9406	Surveyors	Mrs. Gladys Norman, Brambles, Minorca Hill, LAXEY, IM4 7DX, 07624478272, graglad@manx.net		08-11-2023	00:00

Notes : Look at conservatory Duettes - replace?

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Conservatory	1	1885	BS	1222	22	4010 TUBULE Stone				L PVC	
	1	1265	BS	1222	-					L CRF	
	1	975	BS	1200	-					R	
Doors	1	563	BS	1930	2.1	BB11 - Hand					
	1	583	BS	-	-	BB11 - Hand					
	1	970	BS	1200	2.2					L PVC	
	1	1290	BS	1200	-					R CRF	
	1	1892	BS	1200	-					L	
		CRF									
	1	488	CS	1818		Beed - 15mm					
	1	488	CS	1812		Beed - 15mm					