Staff Name Andrew

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS9637	Surveyors	Mr & Mrs. Stobart, 2 BALLAGLONNEY CLOSE, CROSBY, ISLE OF MAN, IM4 2DH, 07624 401621, stobart_hilary@manx.net Ardery, Somerset Road, Douglas, Isle of man, I M,		15-01-2024	00:00

Notes : Ven in dining room, repair or replace? En-suite roller, same as had.
Near traffic lights, on corner by the lane op side to the vets.

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Din	1	2465	R	1555	2 4 8	m/B Ven 4806	25			Top Fix	Drill.
Back											
Shower	1	357	R	1300		R/B				RHS/L off	£3000
						Old Stock			W.	+ Fix	
						Any Price.					
						Please Quote					