Staff Name Chris

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS10256	Surveyors	Mrs. Rimmer, 59 Reayrt Y Chrink, Port Erin, Isle Of Man, IM9, 835517,		12-06-2024	15:00

Notes : Measure for black-out roller blind and look at broken blind please. Take samples

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Lounge	1	1477	R	1575		Polaris Blat Satin				PVC cue	
										and metal chain	
Bed	1	1468	R	1570		repair blind?				MC	