Staff Name Chris

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS10285	Surveyors	Mr. A Patrick, 21 Vicarage Park, Braddan, Isle Of Man, IM2 2QD, 07624 314311, alan.patrick@manx.net		18-06-2024	16:30

Notes : multishade blind torn - replace?

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Cloak	1	587	R	1005		M-SMOKE 8023				MAC	
		560	MW							FW / USE OLD HOLES	