Staff Name Chris

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS10294	Surveyors	Mr. Golt, 50 Ballbrooie Way, Douglas, Isle Of Man, IM1 4ES, 07624310820, 675121, jgalt@manx.net		20-06-2024	16:15

Notes : Bay window curtain track come down ,needs replacement.

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
	1	350	x			SYMPLE CURTAIN				TRY USE	
						+ HOOKS!				OLD RODS	