Staff Name Andrew

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS10544	Surveyors	Mrs. Barbara Ogden, 2 CROIT-E-CUBBON, COLBY, ISLE OF MAN, IM9 4NN, 832878, 07624 322993, barbarabridgeogden@btinternet.com		09-08-2024	16:00

Notes :

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
	3	~~[illegible]~~	~~[illegible]~~			R/B BLIND WITH BOATS ON ??					
LH WINDOW	1	1080	R	1700	2 8 8		32		W	LHS/C	WOOD FRM
										RHS/C	" "
RH WINDOW	1	1080	R	"	"		"		"		
						DRILL [redacted] HOLES SO DON'T SPLIT WOOD					