Staff Name Chris

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS10555	Surveyors	Mrs. Denner, 19 King Orry Road, Glen Vine, Isle Of Man, IM4 4ES, 852879, ann.denner@manx.net		14-08-2024	14:00

Work Diary

Notes : Roller in bathroom, take samples, also look at conservatory, old Vertical tracks so explained will need to be replaced, .

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Bathroom	1	877	R	960		Vera silver				BRC / very STD	
Lounge	1	1780	R	LATT						LM/LH PVC CHR	x 90-DM
	1	3980	R	LATT						RLH / FACER	
	1	2870	R	LATT						RLR/LH	x 90 BAY