1600

Staff Name Andrew

Work Diary

Order No	Surveyor	Contact Address	Customer Ref	Date	Ti
TS10734	Surveyors	Mr. Stephen Gawne, 78 WESTBOURNE DRIVE, DOUGLAS, ISLE OF MAN, IM2, 07624 239229, stevie_gawne@outlook.com		24-09-2024	09

Notes : Bay window, has old vertical track, explained expensive to replace, looking at sologlyde track and Voiles, or Cameron Fuller bay track and curtains.

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instruc
	1	320		161		Tight Drop. IF CURTS ON	CAM FULLER BAY TRACK.				TOP P/B
				Tight							
	1	320		1600		SOLOGLIDE FIX TO PVC FRAME	FIX PVC.				
				TIGHT		IF VOILE.					
						ALLOWANCES TO BE TAKEN					
						OFF WHEN CHOSEN TRACK ETC					