Staff Name Chris

Measuring Sheet.

Order No	Surveyor	Contact Address	Customer Ref	Date	Time
TS11902	Measurer	MrsMoore3 Pine Hill, Highton Wood Hill, Douglas, Isle of Man, IM2, 01624674863, elmo@manx.net MrsMoore3 Pine Hill, Highton Wood Hill, Douglas, Isle of Man, IM2, 01624674863, elmo@manx.net		09-05-2025	14:00:00-14:30:0

Notes : Vertical Track damaged - repair or replace?

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
	1	3850	R	2100		New 89mm track				25 each	rich
										RM	
										and chain	