

Staff Name Chris

### Measuring Sheet.

Order No TS12259

Surveyor Measurer

Contact Address  
Mr.A. Campbell, Parvus Limited KIRBY VIEW, BALLASTOWELL, VICARAGE ROAD,  
BRADDAN, ISLE OF MAN, IM4 2AD, 07624 494867, ackirby@manx.net  
Mr. Campbell 56 Meadow Crescent, Saddlestone, IM2

Customer Ref

Date 24-07-2025

Time 16:00:00-17:00:00

#### Notes :

Room	Qty	Width	FW R B	Drop	R HH	Product Description	Size	Price Code	HW Col	Cont./Fixings	Special Instructions
Kit	1	1715	R	1000		- cords broken	slat degradation			wash free	Blind damaged
Dining	1	2300	X	228		eyelid cords (x pair)					cords ok (blinds damaged)
Garage	1	179	R	200		W/LM Slat vial				TOP Down	
	1	700	R	1157		W/LM					
	1	1755	R	-		RM/SWIR				slat vial	blinds faces
	1	700	R	-		RM/AM					
Bath	1	2200	X	227		eyelid cords (x row)					
Bath Bed	1	1140	R	987		roller / ven				wash free	roller okay
RM Bed	1	1740	R	1160						RM / SWIR	
	1	700	X	137		cords - pencil (blind)					cords faded
RM Bed	1	1170	R	1160						RM / AM	
	1	148	X	143		cords + pencil					old hole top
RM Bed	1	1175	R	1160						RM / AM	
	1	147	X	147		eyelid cords,					old + faded

+ Pairs - one substituted